

Professional Audio Service Bulletin

Mincom
Division



BULLETIN NO. 8

Subject: Modification to Eliminate Possible Sync Oscillation

Applicable to: All M-79 Professional Audio Recorders

Procedure:

- 1) Remove power from machine.
- 2) Remove Track 1 Signal Electronics board from housing.
- 3) Remove L-10, 100uh coil and replace with 110 ohm, 1/4W, 5% resistor (Mincom Catalog No. 83-9520-2131 or 83-1520-0353).
- 4) Remove C-54, .0047uf capacitor and replace with 75k ohm, 1/4W, 5% resistor (Mincom Catalog No. 83-9520-2171 or 83-1520-0377).
- 5) Repeat steps 3 and 4 for each Signal Electronics board in the particular M-79 that is to be modified.
- 6) Change Signal Electronics board schematic to reflect these changes.

February 1974

Professional Audio Service Bulletin



BULLETIN NO. 8

Bulletin No.
Date

Subject: Modification to Eliminate Possible Sync Oscillation

Applicable to: All M-79 Professional Audio Recorders

Procedure:

- 1) Remove power from machine.
- 2) Remove Track 1 Signal Electronics board from housing.
- 3) Remove L-10, 100uh coil and replace with 110 ohm, 1/4W, 5% resistor (Mincom Catalog No. 83-9520-2131 or 83-1520-0353).
- 4) Remove C-54, .0047uf capacitor and replace with 75k ohm, 1/4W, 5% resistor (Mincom Catalog No. 83-9520-2171 or 83-1520-0377).
- 5) Repeat steps 3 and 4 for each Signal Electronics board in the particular M-79 that is to be modified.
- 6) Change Signal Electronics board schematic to reflect these changes.

February 1974